


Unplug Lightstrip



1


REMOVE

Plastic Surrounding Lightstrip




2

CUT in Middle of Solder Points



3 INSERT Lightstrip



4 CLOSE Connector

